

Service Report



WORK ORDER ID: CWKD4080819

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: KUMC RESEARCH INSTITUTE | DEPARTMENT: 190215-KUMC RESEARCH INSTITUTE-ROUNDS RESEARCH INSTITUTE | ACCOUNT NUMBER: 190215

CONTACT:

CUSTOMER PO#:

CONTACT PHONE:

CUSTOMER REFERENCE:

BILLING ADDRESS: PO Box 3160 Kansas City, KS 66103

SHIPPING ADDRESS: 4330 Shawnee Mission Pkwy, Ste. #1360 Fairway, KS 66205

AGILITI ASSET ID : 1887902 | SERIAL #: 20258294 | VENDOR SITE ID: | CUSTOMER ASSET ID:

ASSET TYPE: THERMOMETERS, ELECTRONIC | MANUFACTURER: WELCH ALLYN INC A SUBSIDIARY OF HILLROM HOLDINGS INC | MODEL: SURETEMP PLUS 690

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887902

SERVICE PROVIDED TYPE: Scheduled Maintenance

WORK COMPLETED: 01-23-2024

LABOR

| SERVICE PROVIDER | CATEGORY | HOURS | PERIOD DEFINITION | SERVICE DATE |
|-------------------|----------------|-------|-------------------|--------------|
| Marcus Boatwright | PM Not Covered | 0.3 | M-F 8-5 | 01/23/24 |

SERVICE PROVIDED DETAILS

Completed SM passed all inspection testing

CHECKLIST

PROCEDURE: SURETEMP PLUS 690

QUESTION

Inspect unit for damage, labels and loose screws
Is a temp probe supplied and available for use?

ANSWER

Pass
Yes

Install Batteries (3 AA)

Power on unit and perform Power on Self test

Remove any probe and connect Sure temp Plus Calibration Key (PN 06138-000)

After 60 seconds, record temp reading (Degree F)

Remove calibration key and replace sure temp probe

Using the model 9600 Calibration tester set to 96.4 deg F, test the temp probe (Degree F)

Change the temp setting on the 9600 calibration tester to 106 deg F and repeat the test (Degree F)

Pass

Pass

Pass

97.3

Pass

N/A

N/A

Customer Signature:

Date:

Technician Signature:

Date: