

# Service Report



## WORK ORDER ID: CWKD4080818

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: KUMC RESEARCH INSTITUTE | DEPARTMENT: 190215-KUMC RESEARCH INSTITUTE-ROUNDS RESEARCH INSTITUTE | ACCOUNT NUMBER: 190215

CONTACT:

CUSTOMER PO#:

CONTACT PHONE:

CUSTOMER REFERENCE:

BILLING ADDRESS: PO Box 3160 Kansas City, KS 66103

SHIPPING ADDRESS: 4330 Shawnee Mission Pkwy. Ste. #1360 Fairway, KS 66205

AGILITI ASSET ID : 1887907 | SERIAL #: 20258164 | VENDOR SITE ID: | CUSTOMER ASSET ID:

ASSET TYPE: THERMOMETERS, ELECTRONIC | MANUFACTURER: WELCH ALLYN INC A SUBSIDIARY OF HILLROM HOLDINGS INC | MODEL: SURETEMP PLUS 690

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887907

SERVICE PROVIDED TYPE: Scheduled Maintenance

WORK COMPLETED: 01-23-2024

### LABOR

SERVICE PROVIDER	CATEGORY	HOURS	PERIOD DEFINITION	SERVICE DATE
Marcus Boatwright	PM Not Covered	0.3	M-F 8-5	01/23/24

### SERVICE PROVIDED DETAILS

Completed SM passed all inspection testing

### CHECKLIST

PROCEDURE: SURETEMP PLUS 690

#### QUESTION

Inspect unit for damage, labels and loose screws  
Is a temp probe supplied and available for use?

#### ANSWER

Pass  
Yes

**Install Batteries (3 AA)**

Power on unit and perform Power on Self test

Remove any probe and connect Sure temp Plus Calibration Key (PN 06138-000)

After 60 seconds, record temp reading ( Degree F )

Remove calibration key and replace sure temp probe

Using the model 9600 Calibration tester set to 96.4 deg F, test the temp probe ( Degree F )

Change the temp setting on the 9600 calibration tester to 106 deg F and repeat the test ( Degree F )

Pass

Pass

Pass

97.3

Pass

N/A

N/A

---

Customer Signature:

Date:

---

Technician Signature:

Date: