COBB LAB SERVICE 8071 Flint St. Lenexa, KS 66214 PHONE 816 356-8262

Centrifuge Performance Report

Customer	Inf	~ ~ ~~	:-	
Customer	т	ווזוט	auc	m.

Address: 4001 Dr. Martin Luther King Jr. Blvd							State: MO	Zip 64130		
Contact Person:	Tricia Sno	w	816-398-8	960						Fax:
Equipment Information:										
Name/Model:	Thermo/S				Serial N./Department ID: 42665624					
Date Certified:				Date Due: 11/2023						
Physical Condition:										
Chassis / Housing			Pass X		Fail	_				
Controls & Switches			Pass X		Fail	_				
Power Cord & Strain I	Relief		Pass X		Fail	_				
Hardware Integrity			Pass X		Fail	_				
Indicators & Display (Operation		Pass X		Fail	_				
Mfg. Labeling Intact			Pass X		Fail	_				
Condenser Filter Repl	aced		Pass		Fail NA	_				
Operation:										
Timer Accuracy	Unit		Cert time	2:	5min	Pass	Χ		Fail	
Lid Latch Safety Interl	lock					Pass	Χ		Fail	
Brake						Pass	Χ		Fail	
Speed Check Low		Set		300	Measured			300.02		
Speed Check Med		Set		2500	Measured			2500.3		
Speed Check High		Set		5,000	Measured			4999.4		
Temperature		Set		NA	Measured			NA		
Electrical:										
Line Voltage										
Hot Neutral			V RMS		116					
Neutral Ground			V RMS		0.01	•				
Hot Ground			V RMS		116	•				
Power cord resistance	e		O HMS		8	_				
Equipment Current			A RMS		115					
Leakage Test/Equip. F	Power off					='				
Case Ext. Normal Pol.										
Closed Ground & Neu	ıtral		uA RMS		0					
Open Ground/Closed	Neutral		uARMS		0					
Leakage Test/Equipm	ent Powe	r Or	1		0	_				
Closed Ground & Neu	ıtral		uA RMS		0					
open Ground/Closed	Neutral		uA RMS		0	-				
		INS	TRUMEN	NT CEI	RTIFICATIO	N IN	FOR	MATION	J	
MANUFACTUR	RER: Mona	rch		М	odel:PLT200				SERIAL NUMBER	R: 1041677

CERTIFICATION DATE:03/12/2021 CERTIFICATION DUE: 03/12/2023

CERTIFICATION #: 00073475

METHOD: Certified per manufacturer's specifications and procedures traceable to NIST.

SERVICE TECHNICIAN: Jim Cowart REPORT DATE: 11/14/2022