

Service Report



WORK ORDER ID: CWKD4082835

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: KUMC RESEARCH INSTITUTE | **DEPARTMENT:** 190215-KUMC RESEARCH INSTITUTE-ROUNDS RESEARCH INSTITUTE | **ACCOUNT NUMBER:** 190215

CONTACT:

CUSTOMER PO#:

CONTACT PHONE:

CUSTOMER REFERENCE:

BILLING ADDRESS: PO Box 3160 Kansas City, KS 66103

SHIPPING ADDRESS: 4330 Shawnee Mission Pkwy, Ste. #1360 Fairway, KS 66205

AGILITY ASSET ID : 1887911 | **SERIAL #:** 115070245345 | **VENDOR SITE ID :** | **CUSTOMER ASSET ID:**

ASSET TYPE: ELECTROCARDIOGRAPHS, MULTICHANNEL, INTERPRETIVE | **MANUFACTURER:** WELCH ALLYN INC A SUBSIDIARY OF HILLROM HOLDINGS INC | **MODEL:** ELI 280

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887911

SERVICE PROVIDED TYPE: Scheduled Maintenance

WORK COMPLETED: 01-23-2024

LABOR

SERVICE PROVIDER	CATEGORY	HOURS	PERIOD DEFINITION	SERVICE DATE
Kirstin Williams	PM Not Covered	0.5	M-F 8-5	01/23/24

SERVICE PROVIDED DETAILS

Performed SM per OEM specifications. All test passed.

TEST EQUIPMENT

PREFIX	UNIT	DESCRIPTION	CALIBRATION DATE
DF9	137	DEFIB ANALYZER, IMPULSE 7000DP	05/04/23

CHECKLIST

PROCEDURE: M1230 L1

QUESTION	ANSWER
CABLES	Pass
CALIBRATION	Pass
CLEAN	Yes
CLEAN	Yes
CLEAN/LUBE REC.	Yes
Clinical- Audio	Pass
Clinical- Visual	Pass
CONNECTORS	Pass
Electrical Safety Inspection	Pass
EXT CONDITION	Pass
MECH	Pass
Mechanical Safety Inspection	Pass
Operational Check	Pass
Patient- Audio	Pass
Patient- Visual	Pass
PLUGS	Pass
Remote	Pass
Safety- Audio	Pass
Safety- Visual	Pass
SPEED	Pass
STYLUS/PRINTHEA	Yes
WAVEFORM	Pass

Customer Signature:

Date:

Technician Signature:

Date: