

COBB Refrigeration LLC

913-403-0088 • www.cobbrls.com

Centrifuge Performance Report

Customer: University of Kansas Health Syst-CTSU (Fairway)	Contact: Shelby Willams
Street: 4350 Shawnee Mission Pkw	Phone #: 913-574-3018

Asset#	Model#	MFG	S/N	Electrical Safety Check	Condition Controls/ Switches	Condition Power Cord & Strin Relief	+/- 2 C=Pass		P= Pass	F=Fail	Timer Accuracy P/F	Lid Latch Safety Interlock	Brake	Speed Check Low		Speed Check Med		Speed Check High		Temperature°C		
							Hardware Integrity	Indecators & Display Operation	MFG. Labeling Intact	Cond. Filter Cleaned				Set	Measured	Set	Measured	Set	Measured	Set	Measured	
F-6	X-30R	BECKMAN	ALZ14J022	P	P	P	P	P	P	P	P	P	P	100	100.1	2500	2499.9	4700	4699.9	15	16.1	
F-7	X-30R	BECKMAN	ALZ15J022	P	P	P	P	P	P	P	P	P	P	100	99.80	2500	2499.2	4700	4699.4	4	4.8	
F-8	X-30R	BECKMAN	ALZ19A019	P	P	P	P	P	P	P	P	P	P	100	99.47	2500	2500.8	4700	4701.4	3	2.9	
F-9	X-30R	BECKMAN	ALZ19A024	P	P	P	P	P	P	P	P	P	P	100	101.20	2500	2499.7	4700	4700.0	19	19.2	
F-10	75003539	THERMO	40652297	P	P	P	P	P	P	P	P	P	P	1600	1624.2	2000	2014.2	5000	5049.0	NA	NA	
F-11	5702R	EPPENDORF	5703BM311349	P	P	P	P	P	P	P	P	P	P	100	100.4	1500	1500.3	4400	4399.6	22	22.5	
F-12	5702R	EPPENDORF	6398	P	P	P	P	P	P	P	P	P	P	100	100.52	1500	1502.1	4400	4398.7	22	22.8	
F-16	420225	CLAY ADAMS	4040054	P	P	P	P	P	P	P	P	P	P	3500	3481	SINGLE SPEED			NA	NA		

Test equipment used
 Monarch PLT200 Laser Tach 200, S/N: 1041677, EX Date 03/12/2022 Cert#: 00071091

Technician: Jim Cowart
 Date: 1/28/2022

Notes: Next Due 01/2023

Calibration Performed by Cobb Refrigeration and Lab Service 8071 Flint St. Lenexa KS, 66212 913-403-0088