

COBB Refrigeration LLC

913-403-0088 • www.cobbrls.com

Centrifuge Performance Report

Customer: University of Kansas Health Syst-CTSU (Fairway)	Contact: Shelby Williams
Street: 4350 Shawnee Mission Pkw	Phone #: 913-574-3018

City/ST/Zip: Fairway, KS 66205				+/- 2 C=Pass		P= Pass		F=Fail													
Asset#	Model#	MFG	S/N	Electrical Safety Check	Condition Controls/ Switches	Condition Power Cord & Strin Relief	Hardware Integrity	Indecators & Display Operation	MFG. Labeling Intact	Cond. Filter Cleaned	Timer Accuracy P/F	Lid Latch Safety Interlock	Brake	Speed Check Low		Speed Check Med		Speed Check High		Temperature©	
														Set	Measured	Set	Measured	Set	Measured	Set	Measured
F-6	X-30R	BECKMAN	ALZ14J022	P	P	P	P	P	P	P	P	P	P	100	102	2500	2500	4700	4700	22	20.6
F-7	X-30R	BECKMAN	ALZ15J022	P	P	P	P	P	P	P	P	P	P	100	99.9	2500	2503	4700	4701.6	4	3.4
F-8	X-30R	BECKMAN	ALZ19A019	P	P	P	P	P	P	P	P	P	P	100	100.54	2500	2500.4	4700	4700.3	4	3.3
F-9	X-30R	BECKMAN	ALZ19A024	P	P	P	P	P	P	P	P	P	P	100	100.3	2500	2501.5	4700	4701.6	22	22.3
F-10	75003539	THERMO	40652297	P	P	P	P	P	P	P	P	P	P	1600	1623	2000	2003.5	5000	5022	NA	NA
F-11	5702R	EPPENDORF	5703BM311349	P	P	P	P	P	P	P	P	P	P	100	101.5	1500	1502	4400	4394	22	22.0
F-12	5702R	EPPENDORF	6398	P	P	P	P	P	P	P	P	P	P	100	100.98	1500	1500.3	4400	4398	22	22.0
F-16	420225	CLAY ADAMS	4040054	P	P	P	P	P	P	P	P	P	P	3500	3357	SINGLE SPEED				NA	NA

Technician:	Jim Cowart
Date:	1/25/2023

Test equipment used	Monarch PLT200 Laser Tach 200, S/N: 1041677, EX Date 04/14/2023 Cert#: 00073475
---------------------	---

Notes:	Next Due 01/2024
--------	------------------

Calibration Performed by Cobb Refrigeration and Lab Service 8071 Flint St. Lenexa KS, 66212 913-403-0088