

**Blood Pressure Monitor Performance Report**

| Customer:    |          | KU-CTSU Fairway                        |                         |                              |                                     | Contact:           |                                | Shelby Williams      |                |      |            |      |           |     |      |                |
|--------------|----------|----------------------------------------|-------------------------|------------------------------|-------------------------------------|--------------------|--------------------------------|----------------------|----------------|------|------------|------|-----------|-----|------|----------------|
| Street:      |          | 4350 Shawnee Mission Parkway 3rd Floor |                         |                              |                                     | Phone #            |                                | 913-574-3018         |                |      |            |      |           |     |      |                |
| City/ST/Zip: |          | Fairway, KS 66205                      |                         |                              |                                     | P= Pass    F=Fail  |                                |                      |                |      |            |      |           |     |      |                |
| MFG          | Model#   | S/N                                    | Electrical Safety Check | Condition Controls/ Switches | Condition Power Cord & Strin Relief | Hardware Integrity | Indecators & Display Operation | MFG. Labeling Intact | Normal         |      | Hypertonic |      | Hypotonic |     | SPO2 |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      | 120/80         | P 60 | 200/150    | P130 | 60/30     | P40 | 97%  | Date Performed |
| Hillrom      | (91)73WX | (21)100093400821                       | P                       | P                            | P                                   | P                  | P                              | P                    | 122/82         | 60   | 202/149    | 130  | 60/32     | 40  | 97%  | 1/26/2023      |
| Hillrom      | (91)73WX | (21)100093500821                       | P                       | P                            | P                                   | P                  | P                              | P                    | 120/80         | 60   | 120/80     | 130  | 60/32     | 40  | 97%  | 1/26/2023      |
| Hillrom      | (91)73WX | (21)100093440821                       | P                       | P                            | P                                   | P                  | P                              | P                    | 121/82         | 60   | 121/82     | 130  | 61/32     | 40  | 97%  | 1/26/2023      |
| Hillrom      | (91)73WX | (21)100093430821                       | P                       | P                            | P                                   | P                  | P                              | P                    | 121/82         | 60   | 202/149    | 130  | 62/32     | 40  | 97%  | 1/26/2023      |
| Hillrom      | (91)73WX | (21)100093510821                       | P                       | P                            | P                                   | P                  | P                              | P                    | MISSING        |      |            |      |           |     |      |                |
| Hillrom      | (91)73WX | (21)100093460821                       | P                       | P                            | P                                   | P                  | P                              | P                    | OUT OF SERVICE |      |            |      |           |     |      |                |
| Hillrom      | (91)73WX | (21)100093420821                       | P                       | P                            | P                                   | P                  | P                              | P                    | MISSING        |      |            |      |           |     |      |                |
| Hillrom      | (91)73WX | (21)100093450821                       | P                       | P                            | P                                   | P                  | P                              | P                    | 121/81         | 60   | 202/151    | 130  | 60/32     | 40  | 97%  | 1/26/2023      |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |
|              |          |                                        |                         |                              |                                     |                    |                                |                      |                |      |            |      |           |     |      |                |

|             |    |
|-------------|----|
| Technicians | JC |
| Initials    |    |

Technician: Jim Cowart  
**Date: 01/26/2023**

Test equipment used  
**FLUKE- ProSim 8 S#399003 Expires:09/07/2023**

Notes: Next Due Date: 01/2024  
**Calibration Performed by Cobb Refrigeration and Lab Service 8071 Flint St. Lenexa KS, 66212 913-403-0088**

**Blood Pressure Monitor Performance Report**

| <b>Customer:</b> KU-CTSU Fairway                      |        |     | <b>Contact:</b> Shelby Williams |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
|-------------------------------------------------------|--------|-----|---------------------------------|---------------------------------|-------------------------------------------|-----------------------|--------------------------------------|-------------------------|--------|------|------------|------|-----------|-----|------|----------------|
| <b>Street:</b> 4350 Shawnee Mission Parkway 3rd Floor |        |     | <b>Phone #</b> 913-574-3018     |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
| <b>City/ST/Zip:</b> Fairway, KS 66205                 |        |     | P= Pass    F=Fail               |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
| MFG                                                   | Model# | S/N | Electrical Safety<br>Check      | Condition<br>Controls/ Switches | Condition Power<br>Cord & Strin<br>Relief | Hardware<br>Integrity | Indecators &<br>Display<br>Operation | MFG. Labeling<br>Intact | Normal |      | Hypertonic |      | Hypotonic |     | SPO2 | Date Performed |
|                                                       |        |     |                                 |                                 |                                           |                       |                                      |                         | 120/80 | P 60 | 200/150    | P130 | 60/30     | P40 | 97%  |                |

**Blood Pressure Monitor Performance Report**

| <b>Customer:</b> KU-CTSU Fairway                      |        |     | <b>Contact:</b> Shelby Williams |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
|-------------------------------------------------------|--------|-----|---------------------------------|---------------------------------|-------------------------------------------|-----------------------|--------------------------------------|-------------------------|--------|------|------------|------|-----------|-----|------|----------------|
| <b>Street:</b> 4350 Shawnee Mission Parkway 3rd Floor |        |     | <b>Phone #</b> 913-574-3018     |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
| <b>City/ST/Zip:</b> Fairway, KS 66205                 |        |     | P= Pass    F=Fail               |                                 |                                           |                       |                                      |                         |        |      |            |      |           |     |      |                |
| MFG                                                   | Model# | S/N | Electrical Safety<br>Check      | Condition<br>Controls/ Switches | Condition Power<br>Cord & Strin<br>Relief | Hardware<br>Integrity | Indecators &<br>Display<br>Operation | MFG. Labeling<br>Intact | Normal |      | Hypertonic |      | Hypotonic |     | SPO2 | Date Performed |
|                                                       |        |     |                                 |                                 |                                           |                       |                                      |                         | 120/80 | P 60 | 200/150    | P130 | 60/30     | P40 | 97%  |                |