

COBB Refrigeration LLC

913-403-0088 • www.cobbrls.com

Centrifuge Performance Report

Customer: University of Kansas Health Syst-CTSU (Rainbow)(Sudler 2012)										Contact: Shelby Williams											
Street: 3901 Rainbow										Phone #: 913-574-3018											
City/ST/Zip: Kansas City, KS 66160										+/- 2 C=Pass		P= Pass		F=Fail							
Asset#	Model#	MFG	S/N	Electrical Safety Check	Condition Controls/ Switches	Condition Power Cord & Strin Relief	Hardware Integrity	Indecators & Display Operation	MFG. Labeling intact	Cond. Filter Cleaned	Timer Accuracy P/F	Lid Latch Safety Interlock	Brake	Speed Check Low		Speed Check Med		Speed Check High		Temperature©	
														Set	Measured	Set	Measured	Set	Measured	Set	Measured
S-6	X-30R	BECKMAN	64424100	P	P	P	P	P	P	P	P	P	P	100	101.2	2500	2499.3	4700	4701.1	5	4.8
S-7	X-30R	BECKMAN	64428135	P	P	P	P	P	P	P	P	P	P	100	100.2	2500	2500.1	4700	4699.8	20	18.9
S-8	X-30R	BECKMAN	64428105	P	P	P	P	P	P	P	P	P	P	100	100.5	2500	2500.7	4700	4700.3	3	2.8
S-9	5702R	EPPENDORF	5703BM311350	P	P	P	P	P	P	P	P	P	P	100	101.6	2500	2501.4	4400	4396.8	23	22.1
DELP G040																					
S-5	X-30R	BECKMAN	64426102	P	P	P	P	P	P	P	P	P	P	100	101.1	2500	2499.8	4700	4699.5	22	21.5
S-10	X-30R	BECKMAN	80549004	P	P	P	P	P	P	P	P	P	P	100	100.0	2500	2501.4	4701	4700.6	4	5.1

Test equipment used

Technician: Jim Cowart

Date: 1/12/2023

Monarch PLT200 Laser Tach 200, S/N: 1041677, EX Date 04/14/2023

Notes: Next Due 01/2024

Calibration Performed by Cobb Refrigeration and Lab Service 8071 Flint St. Lenexa KS, 66212 913-403-0088