

**Centrifuge Performance Report**

<b>Customer:</b> University of Kansas Health Syst-CTSU (Rainbow)(Sudler 2012)	<b>Contact:</b> Shelby Williams
<b>Street:</b> 3901 Rainbow	<b>Phone #:</b> 913-574-3018

<b>City/ST/Zip:</b> Kansas City, KS 66160				<b>+/- 2 C=Pass</b>		<b>P= Pass</b>		<b>F=Fail</b>													
Asset#	Model#	MFG	S/N	Electrical Safety Check	Condition Controls/ Switches	Condition Power Cord & Strin Relief	Hardware Integrity	Indecators & Display Operation	MFG. Labeling Intact	Cond. Filter Cleaned	Timer Accuracy P/F	Lid Latch Safety Interlock	Brake	Speed Check Low		Speed Check Med		Speed Check High		Temperature©	
														Set	Measured	Set	Measured	Set	Measured	Set	Measured

S-6	X-30R	BECKMAN	64424100	P	P	P	P	P	P	P	P	P	P	100	101.1	2500	2500.1	4700	4700.8	22	22.8
S-7	X-30R	BECKMAN	64428135	P	P	P	P	P	P	P	P	P	P	100	100.69	2500	2499.4	4700	4699.8	3	2.1
S-8	X-30R	BECKMAN	64428105	P	P	P	P	P	P	P	P	P	P	100	100.17	2500	2499.4	4700	4699.7	10	9.4
S-9	5702R	EPPENDORF	5703BM311350	P	P	P	P	P	P	P	P	P	P	100	100.2	2500	2498.1	4400	4387.4	21	22.1
<b>DELP G040</b>																					

S-5	X-30R	BECKMAN	64426102	P	P	P	P	P	P	P	P	P	P	100	99.3	2500	2501.3	4700	4699.9	21	22.4
S-10	X-30R	BECKMAN	80549004	P	P	P	P	P	P	P	P	P	P	100	100.2	2500	2499.8	4701	4699.2	22	22.2

**Test equipment used**  
 Monarch PLT200 Laser Tach 200, S/N: 1041677, EX Date 03/12/2022 Cert#: 00071091

Technician: Jim Cowart  
**Date: 1/18/2022**

Notes: Next Due 01/2023

**Calibration Performed by Cobb Refrigeration and Lab Service 8071 Flint St. Lenexa KS, 66212 913-403-0088**