

Service Report



WORK ORDER ID: CWKD4081774

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: KUMC RESEARCH INSTITUTE | DEPARTMENT: 190215-KUMC RESEARCH INSTITUTE-ROUNDS RESEARCH INSTITUTE | ACCOUNT NUMBER: 190215

CONTACT:

CUSTOMER PO#:

CONTACT PHONE:

CUSTOMER REFERENCE:

BILLING ADDRESS: PO Box 3160 Kansas City, KS 66103

SHIPPING ADDRESS: 4330 Shawnee Mission Pkwy. Ste. #1360 Fairway, KS 66205

AGILITI ASSET ID : 1887935 | SERIAL #: E14019-0058 | VENDOR SITE ID: | CUSTOMER ASSET ID:

ASSET TYPE: SCALES, PATIENT, FLOOR | MANUFACTURER: DETECTO - A DIVISION OF CARDINAL SCALE MANUFACTURING CO. | MODEL: MEDVUE

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887935

SERVICE PROVIDED TYPE: Scheduled Maintenance

WORK COMPLETED: 01-23-2024

LABOR

SERVICE PROVIDER	CATEGORY	HOURS	PERIOD DEFINITION	SERVICE DATE
Stephanie Harper	PM Not Covered	0.3	M-F 8-5	01/23/24

SERVICE PROVIDED DETAILS

Completed SM passed inspection testing

TEST EQUIPMENT

PREFIX	UNIT	DESCRIPTION	CALIBRATION DATE
WT1	689	WEIGHT, 50 LBS	04/14/23

CHECKLIST

PROCEDURE: B3800 L1

QUESTION

Electrical Safety Inspection
HEAVY WT ACTUAL
HEAVY WT DISPLA
LIGHT WT ACTUAL
LIGHT WT DISPLA
Mechanical Safety Inspection
Operational Check

ANSWER

Pass
50
50.4
N/A
N/A
Pass
Pass

Customer Signature:

Date:

Technician Signature:

Date: