Service Report



WORK ORDER ID: CWKD4070913

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: UNIV OF KS MED CTR-CTSU RNBW | DEPARTMENT: 177820-UNIV OF KS MED CTR-CTSU RNBW-ROUNDS CTSU RNBW | ACCOUNT NUMBER: 177820

CONTACT: CUSTOMER PO#:

CONTACT PHONE: CUSTOMER REFERENCE:

BILLING ADDRESS: 3901 Rainbow Blvd MS 1077 2012 Suder Kansas City, KS 66160 SHIPPING ADDRESS: 3901 Rainbow Blvd MS 1077 2012 Suder Kansas City, KS 66160

AGILITI ASSET ID: 1887877 | SERIAL #: 12223000333 | VENDOR SITE ID: | CUSTOMER ASSET ID:

ASSET TYPE: ELECTROCARDIOGRAPHS, MULTICHANNEL, INTERPRETIVE | MANUFACTURER: WELCH ALLYN INC A SUBSIDIARY OF HILLROM HOLDINGS INC | MODEL: ELI

280

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887877

SERVICE PROVIDED TYPE: Scheduled Maintenance

WORK COMPLETED: 01-19-2024

LABOR

SERVICE PROVIDER	CATEGORY	HOURS	PERIOD DEFINITION	SERVICE DATE
Stephanie Harper	PM Not Covered	0.22	M-F 8-5	01/19/24
Marcus Boatwright	PM Not Covered	0.22	M-F 8-5	01/19/24

SERVICE PROVIDED DETAILS

Completed SM passed all inspection testing 98/42 ES

TEST EQUIPMENT

PREFIXUNITDESCRIPTIONCALIBRATION DATESB6223SAFETY ANALYZER, FLUKE ESA61204/25/23

 PR2
 133
 SIMCUBE-ORDERED WITH OXSIM
 04/14/23

 PR3
 473
 OXIMETER SIMULATOR
 04/14/23

CHECKLIST	
-----------	--

PROCEDURE: M1230 L1		
QUESTION		ANSWER
CABLES		Pass
CALIBRATION		Pass
CLEAN		Yes
CLEAN		Yes
CLEAN/LUBE REC.		Yes
Clinical- Audio		Pass
Clinical- Visual		Pass
CONNECTORS		Pass
Electrical Safety Inspection		Pass
EXT CONDITION		Pass
MECH		Pass
Mechanical Safety Inspection		Pass
Operational Check		Pass
Patient- Audio		Pass
Patient- Visual		Pass
PLUGS		Pass
Remote		Pass
Safety- Audio		Pass
Safety- Visual		Pass
SPEED		Pass
STYLUS/PRINTHEA		Yes
WAVEFORM		Pass
Customer Signature:	Date:	
Technician Signature:	Date:	