## **Service Report**



## WORK ORDER ID: CWKD4101268

WORK ORDER TYPE: Preventative Maintenance

CUSTOMER: UNIV OF KS MED CTR-CTSU RNBW | DEPARTMENT: 177820-UNIV OF KS MED CTR-CTSU RNBW-ROUNDS CTSU RNBW | ACCOUNT NUMBER: 177820

CONTACT: CUSTOMER PO#:

CONTACT PHONE: CUSTOMER REFERENCE:

BILLING ADDRESS: 3901 Rainbow Blvd MS 1077 2012 Suder Kansas City, KS 66160 SHIPPING ADDRESS: 3901 Rainbow Blvd MS 1077 2012 Suder Kansas City, KS 66160

AGILITI ASSET ID: 1887948 | SERIAL #: 192423685 | VENDOR SITE ID: | CUSTOMER ASSET ID:

ASSET TYPE: INCUBATORS, LABORATORY, THERMOCYCLING | MANUFACTURER: BOEKEL SCIENTIFIC INC | MODEL: J1672-1

SERVICE REQUESTED: Asset Onboarding - Initial Preventative Maintenance for 1887948

SERVICE PROVIDED TYPE: Scheduled Maintenance

**WORK COMPLETED: 01-30-2024** 

**LABOR** 

SERVICE PROVIDERCATEGORYHOURSPERIOD DEFINITIONSERVICE DATEMarcus BoatwrightPM Not Covered0.3M-F 8-501/30/24

## SERVICE PROVIDED DETAILS

Completed SM passed all inspection testing Temp set to 36c DMM 36.6c

TEST	EQU	IPM	EN	T
------	-----	-----	----	---

PREFIX	UNIT	DESCRIPTION	CALIBRATION DATE
SB6	223	SAFETY ANALYZER, FLUKE ESA612	04/25/23
DM1	286	DIGITAL MULTIMETER	04/14/23

CHECKLIST		
PROCEDURE: L1200 L1		
QUESTION	A	NSWER
Alarm - High Temperature	N	<b>I</b> A
Alarm - Low Temperature	N	<b>I</b> A
CES THERM.	P	ass
Clinical- Audio	P	ass
Clinical- Visual	P	ass
CUST. THERM.	P	ass
DESIRED TEMP	P	ass
Electrical Safety Inspection	P	ass
Mechanical Safety Inspection	P	ass
Operational Check	P	ass
Patient- Audio	P	ass
Patient- Visual	P	ass
Remote	P	ass
Safety- Audio	P	ass
Safety- Visual	P	ass
Customer Signature:	Date:	
Technician Signature:	Date:	